



311141

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: > LANUATI MARINE

PAGE > 2 OF > 7

U.S. EPA ID: > ILD06A496248

TDD: > F05-8810-002

PAN: > FILO277XB12

DATE: > _____

TIME: > _____

DIRECTION OF
PHOTOGRAPH:

> _____

WEATHER
CONDITIONS:

> _____

> _____

PHOTOGRAPHED BY:

> _____

SAMPLE ID
(if applicable):

> S3, S5, MW3, MW4

DESCRIPTION: > WELL NEST MW2, CLOSE-UP, MW2S ON LEFT, MW2D ON RIGHT, SAMPLE S3

> TAKEN FROM MW2S, SAMPLE S5 TAKEN FROM SURFACE IN FOREGROUND, SAMPLE MW3 TAKEN
FROM MW2S, MW4 TAKEN FROM WELL MW1D

DATE: > 6/28/91

TIME: > 0915

DIRECTION OF
PHOTOGRAPH:

> NW

WEATHER
CONDITIONS:

> Sunny

> ~800

PHOTOGRAPHED BY:

> D. BORRETT

SAMPLE ID
(if applicable):

> _____

DESCRIPTION: > WELL NEST MW2, PERSPECTIVE,

> _____

-



FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: > HANNAH MARINE CORP.

PAGE > 3 OF > 7

U.S. EPA ID: > IL0069496248 TDD: > KOS-8810-002

PAN: > F1L0277XBR

DATE: > _____

TIME: > _____

DIRECTION OF
PHOTOGRAPH:

> _____

WEATHER
CONDITIONS:

> _____

> _____

PHOTOGRAPHED BY:

> _____

SAMPLE ID
(if applicable):

> S4, S6, MW 5, MW6

DESCRIPTION: > WELL NEST MW3, CLOSE-UP, MW3S ON RIGHT, MW3D ON LEFT, SAMPLE S4

> TAKEN FROM MW3S, S6 TAKEN FROM SURFACE IN FOREGROUND

GROUNDWATER SAMPLE MW5 TAKEN FROM MW3S, SAMPLE MW6 TAKEN FROM MW3D

DATE: > 6/29/91

TIME: > 1011

DIRECTION OF
PHOTOGRAPH:

> N

WEATHER
CONDITIONS:

> sunny

> v 850

PHOTOGRAPHED BY:

> O. BARRETT

SAMPLE ID
(if applicable):

> _____



DESCRIPTION: > WELL NEST MW3, PERSPECTIVE

> _____

-

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: > HANNAH MARINE CORP.

PAGE > 4 OF > 7

U.S. EPA ID: > IL006996248 TDD: > F-05-8810-002

PAN: > FIL0277XBR

DATE: > 6/29/91

TIME: > 1001

DIRECTION OF PHOTOGRAPH:

> W

WEATHER CONDITIONS:

> SUNNY

> ~85°F

PHOTOGRAPHED BY:

> D. BARRETT

SAMPLE ID (if applicable):

>



DESCRIPTION: > PERSPECTIVE, MAIN BUILDING COMPLEX, NOTE AREA OF DRUM STORAGE

> IN MIDGROUND

DATE: > 6/29/91

TIME: > 1010

DIRECTION OF PHOTOGRAPH:

> NE

WEATHER CONDITIONS:

> SUNNY

> ~85°F

PHOTOGRAPHED BY:

> D. BARRETT

SAMPLE ID (if applicable):

>



DESCRIPTION: > SITE PERSPECTIVE, CHICAGO SANITARY AND SHIP CANAL ON LEFT, RT.

> MAIN OFFICE BUILDING AT MIDGROUND ON RIGHT, 83 OVERPASS IN BACKGROUND

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: > HANNAH MARINE CORP.

PAGE > 5 OF > 7

U.S. EPA ID: > ILD06496248 TDD: > FOS-8810-002

PAN: > FIL 0277X BR

DATE: > 6/29/91

TIME: > 1010

DIRECTION OF
PHOTOGRAPH:

> SW

WEATHER
CONDITIONS:

> SUNNY

> ~85°F

PHOTOGRAPHED BY:

> D. BARRETT

SAMPLE ID
(if applicable):

>



DESCRIPTION: > VACUUM TANK AND FUEL STORAGE TANK AREA, NOTE CONCRETE WALL

> WHICH SURROUNDS AREA

DATE: > 6/29/91

TIME: > 1000

DIRECTION OF
PHOTOGRAPH:

> NW

WEATHER
CONDITIONS:

> SUNNY

> ~85°F

PHOTOGRAPHED BY:

> D. BARRETT

SAMPLE ID
(if applicable):

>



DESCRIPTION: > CLOSEUP OF STORAGE TANKS WITHIN EARTHEN-BERMED AREA,

> NOTE RUST ON TANK IN FOREGROUND

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: > HANNAH MARINE CORP.

PAGE >6 OF > 7

U.S. EPA ID: > ILD06946248

TDD: > FOS-8810-002

PAN: > FLOZ77XBR

DATE: > 6/29/91

TIME: > 0951

DIRECTION OF
PHOTOGRAPH:

> SSW

WEATHER
CONDITIONS:

> SUNNY

> 85°F

PHOTOGRAPHED BY:

> D. BARRETT

SAMPLE ID
(if applicable):

>



DESCRIPTION: > TANK STORAGE AREA, WHITE TANKS ARE WITHIN EARTHEN-BERMED

> AREA, TO THE LEFT TOP OF NEWER TANK IS VISIBLE

DATE: > 6/29/91

TIME: > 0953

DIRECTION OF
PHOTOGRAPH:

> E

WEATHER
CONDITIONS:

> SUNNY

> 85°F

PHOTOGRAPHED BY:

> D. BARRETT

SAMPLE ID
(if applicable):

>



DESCRIPTION: > NEW STORAGE TANK, LOCATED APPROXIMATELY 50 FEET NE OF

> EARTHEN-BERMED AREA

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: HANNAH MARINE CORP.

PAGE 7 OF 7

U.S. EPA ID: TL0069496248

TDD: F05-BB10-002

PAN: FILE277432



DATE: > 6/29/91

TIME: > 0931

DIRECTION OF PHOTOGRAPH: > SW-SE

PHOTOGRAPHED BY: > D. BARRETT

WEATHER CONDITIONS: > sunny w/50%

SAMPLE ID (if applicable): >

DESCRIPTION: EASTERN PORTION OF SITE, BELIEVED TO BE FORMER LAGOON AREAS, STORAGE TANK AREA IN
MIDGROUND AT RIGHT, ROUTE 83 OVERPASS IS REFLECTED IN MIRROR.

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: HANNAH MARINE CORP.

PAGE 1 OF 22

U.S. EPA ID: ILD069496248 TDD: F05-8810-002

PAN: FILO277XBR

DATE: 6/29/91

TIME: 1000

DIRECTION OF
PHOTOGRAPH:

SW

WEATHER
CONDITIONS:

sunny

~85°

PHOTOGRAPHED BY:

D. BARRETT

SAMPLE ID
(if applicable):



DESCRIPTION: This photograph shows 2 dumpsters located east of the tanks which have a dike surrounding it.

DATE: 6/29/91

TIME: 1000

DIRECTION OF
PHOTOGRAPH:

NW

WEATHER
CONDITIONS:

sunny

~85°

PHOTOGRAPHED BY:

D. BARRETT

SAMPLE ID
(if applicable):

DESCRIPTION: This photograph shows the tanks located within a dyked area. Notice the condition of the tank and the breach in the dike in the foreground.

SITE NAME: HANNAH MARINE CORP.PAGE 2 OF 22U.S. EPA ID: IL.D069496248 TDD: F05-8810-002PAN: FIL0277XBRDATE: 6/29/91TIME: 1001DIRECTION OF
PHOTOGRAPH:WWEATHER
CONDITIONS:SUNNY~85°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows an area of drum storage located
northeast of the main building.DATE: 6/29/91TIME: 0950DIRECTION OF
PHOTOGRAPH:SWWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows the facility in the background. The
Chicago Sanitary and Ship Canal is to the right side of the picture.

SITE NAME: HANNAH MARINE CORP.

PAGE 3 OF 22

U.S. EPA ID: ILD069496248 TDD: FOS-8810-002

PAN: FIL0277XBR

DATE: 6/29/91

TIME: 0951

DIRECTION OF
PHOTOGRAPH:

SSW

WEATHER
CONDITIONS:

Sunny

~85°

PHOTOGRAPHED BY:

D. BARRETT

SAMPLE ID
(if applicable):DESCRIPTION: This photograph shows the tanks within the diked area
in the background.

DATE: 6/29/91

TIME: 0952

DIRECTION OF
PHOTOGRAPH:

SE

WEATHER
CONDITIONS:

Sunny

~85°

PHOTOGRAPHED BY:

D. BARRETT

SAMPLE ID
(if applicable):DESCRIPTION: This photograph shows a facility tanker truck that was
parked along the canal. Notice the label that indicates its a special
waste hauler.

SITE NAME: HANNAH MARINE CORPPAGE 4 OF 22U.S. EPA ID: TLDD69496248 TDD: FOS-8810-002PAN: FIL0277XBRDATE: 6/29/91TIME: 0953DIRECTION OF
PHOTOGRAPH:EWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows a tank located northeast of the
diked tank area. Various metal junk is located in the background.DATE: 6/29/91TIME: 0954DIRECTION OF
PHOTOGRAPH:ENEWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BarrettSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows assorted junk located east of the
diked tank area.

SITE NAME: HANNAH MARINE CORPPAGE 5 OF 22U.S. EPA ID: ILD0069496248 TDD: FOS-8810-002PAN: FIL0277XBRDATE: 6/29/91TIME: 1002DIRECTION OF
PHOTOGRAPH:NWWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BarrettSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows the drum storage area located
northeast of the main building.DATE: 6/29/91TIME: 1001DIRECTION OF
PHOTOGRAPH:NWWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BarrettSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows 2 storage sheds. The dike for the
tanks is on the right side of the picture.

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: HANNAH MARINE CORP.

PAGE 6 OF 22

U.S. EPA ID: ILD069496248 TDD: FOS-8810-002

PAN: FILD277YBR

DATE: 6/29/91

TIME: 1002

DIRECTION OF
PHOTOGRAPH:

NNW

WEATHER
CONDITIONS:

SUNNY

~85°

PHOTOGRAPHED BY:

D. BARRETT

SAMPLE ID
(if applicable):



DESCRIPTION: This photograph shows the drum storage area and a storage shed located northeast of the main building.

SITE NAME: HANNAH MARINE CORP.PAGE 8 OF 22U.S. EPA ID: ILD069496248 TDD: F05-8810-002PAN: FILOZ77XBRDATE: 6/29/91TIME: 1010DIRECTION OF
PHOTOGRAPH:SWWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows a tank storage area which is surrounded
by a concrete wall.DATE: 6/29/91TIME: 1010DIRECTION OF
PHOTOGRAPH:WWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows the Chicago Sanitary and Ship canal
located adjacent to the site.

SITE NAME: HANNAH MARINE CORP.PAGE 9 OF 22U.S. EPA ID: ILDO 69496248 TOD: F05-8810-002PAN: FIL0277XBRDATE: 6/29/91TIME: 1010DIRECTION OF
PHOTOGRAPH:NEWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows the Chicago Sanitary and Ship Canal.
The facility is on the right side of the picture.DATE: 6/29/91TIME: 0951DIRECTION OF
PHOTOGRAPH:SWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows the drums generated from the
well boring and development of MW1 shallow and deep.

SITE NAME: HANNAH MARINE CORPPAGE 10 OF 22U.S. EPA ID: ILD069496248 TDD: F05-8810-002 PAN: FIL0217XBRDATE: 6/29/91TIME: 0951DIRECTION OF
PHOTOGRAPH:SWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BarrettSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows a close-up of the drums from M&I
shallow and deep.DATE: 6/7/91TIME: 1450DIRECTION OF
PHOTOGRAPH:SWEATHER
CONDITIONS:Sunny~90°

PHOTOGRAPHED BY:

D. BarrettSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows a turtle that was seen crossing
the road southwest of Route 83.

SITE NAME: HANNAH MARINE CORPPAGE 11 OF 22U.S. EPA ID: ILD069496248 TDD: F05-8810-002 PAN: FILD277XBRDATE: 6/28/91TIME: 0915DIRECTION OF
PHOTOGRAPH:NWEATHER
CONDITIONS:Sunny~80°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):MW3DESCRIPTION: This photograph shows the location of monitoring well
sample MW3 (close-up)DATE: 6/28/91TIME: 0915DIRECTION OF
PHOTOGRAPH:NWWEATHER
CONDITIONS:Sunny~80°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows the location of monitoring well
sample MW3 (distant)

SITE NAME: HANNAH MARINE CORPPAGE 12 OF 22U.S. EPA ID: ILD069496248 TDD: F05-8810-002PAN: FILO277XBRDATE: 6/28/91TIME: 0915DIRECTION OF
PHOTOGRAPH:NWEATHER
CONDITIONS:Sunny~80°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):MW4DESCRIPTION: This photograph shows the location of monitoring well sample MW4 (close-up).DATE: 6/28/91TIME: 0910DIRECTION OF
PHOTOGRAPH:NNWWEATHER
CONDITIONS:Sunny~80°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):MW5DESCRIPTION: This photograph shows the location of monitoring well sample MW5 (distant).

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: HANNAH MARINE CORPPAGE 13 OF 22U.S. EPA ID: ILD069496248 TDD: F05-8810-002PAN: FILO277XBRDATE: 6/28/91TIME: 0910DIRECTION OF
PHOTOGRAPH:
NNWWEATHER
CONDITIONS:Sunny~80°PHOTOGRAPHED BY:
D. BARRETTSAMPLE ID
(if applicable):
MW5DESCRIPTION: This photograph shows the location of monitoring well
sample MW5 (close-up).

SITE NAME: HANNAH MARINE CorpPAGE 14 OF 22U.S. EPA ID: ILD069496248 TDD: F05-8810-002PAN: FIL0277XBRDATE: 6/28/91TIME: 0912DIRECTION OF
PHOTOGRAPH:NNWWEATHER
CONDITIONS:Sunny~80°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):MW6DESCRIPTION: This photograph shows the location of monitoring well sample
MW6 (close-up).DATE: 6/28/91TIME: 0912DIRECTION OF
PHOTOGRAPH:NNWWEATHER
CONDITIONS:Sunny~80°

PHOTOGRAPHED BY:


D. BARRETTSAMPLE ID
(if applicable):MW6DESCRIPTION: This photograph shows the location of monitoring well
sample MW6 (distant).

SITE NAME: HANNAH MARINE CORPPAGE 15 OF 22U.S. EPA ID: ILD069496248 TOD: F05-8810-00ZPAN: F1L0217XBRDATE: 6/29/91TIME: 1011DIRECTION OF
PHOTOGRAPH:NWEATHER
CONDITIONS:SUNNY~85°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):54DESCRIPTION: This photograph shows the location of soil sample 54
(distant)DATE: 6/29/91TIME: 1011DIRECTION OF
PHOTOGRAPH:NNWWEATHER
CONDITIONS:SUNNY~85°


PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):54DESCRIPTION: This photograph shows the location of soil sample 54
(close-up)

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: HANNAH MARINE CORP.PAGE 16 OF 22U.S. EPA ID: ILD069496248 TDD: F05-8810-002PAN: FILO277XBRDATE: 6/29/91TIME: 1012DIRECTION OF
PHOTOGRAPH:NWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):S5DESCRIPTION: This photograph shows the location of soil sample S5 (close-up)DATE: 6/29/91TIME: 1012DIRECTION OF
PHOTOGRAPH:N

WEATHER

CONDITIONS: Sunny ~85°PHOTOGRAPHED BY: D. BARRETTSAMPLE ID
(if applicable): S5DESCRIPTION: This photograph shows the location of soil sample S5 (distant)

SITE NAME: HANNAH MARINE CORPPAGE 17 OF 22U.S. EPA ID: ILD069496248 TDD: F05-8810-002PAN: FILO277XB12DATE: 6/29/91TIME: 1014DIRECTION OF
PHOTOGRAPH:NWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):56DESCRIPTION: This photograph shows the location of soil sample 56 (close-up)DATE: 6/29/91TIME: 1014DIRECTION OF
PHOTOGRAPH:SWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows MW3 & MW4 after the concrete pads were poured.

SITE NAME: HANNAH MARINE CORP.PAGE 18 OF 22U.S. EPA ID: ILD069496248 TDD: FOS-8810-002PAN: FILO277XBRDATE: 6/29/91TIME: 1014DIRECTION OF
PHOTOGRAPH:SWWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows MW3 + MW4 after the concrete pads were
poured and construction complete.DATE: 6/29/91TIME: 1011DIRECTION OF
PHOTOGRAPH:NWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows MW5 + MW6 after the concrete pads
were poured and construction complete.

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: HANNAH MARINE CORP

PAGE 19 OF 22

U.S. EPA ID: ILD069496248 TDD: POS-8810-002

PAN: FILDZ77XBR

DATE: 6/29/91

TIME: 1011

DIRECTION OF
PHOTOGRAPH:
NNW

WEATHER
CONDITIONS:
SUNNY
~85°

PHOTOGRAPHED BY:
D. BARRETT

SAMPLE ID
(if applicable):



DESCRIPTION: This photograph shows MW5 + MW6 after the concrete pads were poured

DATE: 6/10/91

TIME: 1400

DIRECTION OF
PHOTOGRAPH:
NE

WEATHER
CONDITIONS:
cloudy
~85°

PHOTOGRAPHED BY:
D. BARRETT

SAMPLE ID
(if applicable):



DESCRIPTION: This photograph shows the drillers working on MW1.

SITE NAME: HANNAH MARINE CORPPAGE 20 OF 22U.S. EPA ID: ILD069496248 TDD: FOS-8810-002PAN: FILO277XBRDATE: 6/10/91TIME: 1500DIRECTION OF
PHOTOGRAPH:NEWEATHER
CONDITIONS:cloudy~80°PHOTOGRAPHED BY:
D. BARRETTSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows the drillers working on MW1.DATE: 6/18/91TIME: 1005DIRECTION OF
PHOTOGRAPH:WWEATHER
CONDITIONS:Sunny~85°PHOTOGRAPHED BY:
D. BARRETTSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows the damage to a portion of casing from drilling.

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: HANNAH MARINE CORP.PAGE 21 OF 22U.S. EPA ID: ±LD069496248 TDD: FOS-8810-002PAN: FILOZ77XBRDATE: 6/17/91TIME: 1015DIRECTION OF
PHOTOGRAPH:SWEATHER
CONDITIONS:Sunny~85°

PHOTOGRAPHED BY:

D. BARRETTSAMPLE ID
(if applicable):DESCRIPTION: This photograph shows a reaming bit which was damaged during drilling.

FIELD PHOTOGRAPHY LOG SHEET

SITE NAME: HANNAH MARINE CORP.

PAGE 22 OF 22

U.S. EPA ID: ILD069496248 TDD: F05-8810-002

PAN: FILO277XBR

DATE: 6/29/91

TIME: 1014

DIRECTION OF
PHOTOGRAPH: S

WEATHER
CONDITIONS: sunny

PHOTOGRAPHED BY: D. BARRETT

SAMPLE ID
(if applicable): 56

DESCRIPTION: This photograph
shows the location of soil
sample 56 (distant).



DATE: 6/28/91

TIME: 0915

DIRECTION OF
PHOTOGRAPH: NNW

WEATHER
CONDITIONS: sunny
~80°

PHOTOGRAPHED BY: D. BARRETT

SAMPLE ID
(if applicable): MW4

DESCRIPTION: _____



This photograph shows the location of monitoring well MW4 (distant).